

# SAFETY RECALL

## JOHN DEERE D105 LAWN TRACTORS AND SERVICE PART TRANSMISSIONS



Model number

**PROBLEM:** A gear in the transmission in your lawn tractor may not have been manufactured to specification and could fail. If this occurs, the lawn tractor may lose drive, service brake, and parking brake functions. This creates a risk of a crash, which could result in serious injury or death.

**PRODUCT:** This recall involves some D105 John Deere lawn tractors sold from February 2016 through July 2017 and service transmissions sold by John Deere authorized dealers for use in the D105 lawn tractor from March 2016 through August 2017 with the model number and the “John Deere” brand name printed on the hood. The serial number, located on the frame of the machine above the left rear tire, begins with 1GXD105. A complete list of serial numbers included in this recall is located at [www.JohnDeere.com/D105-Transmission-Recall](http://www.JohnDeere.com/D105-Transmission-Recall). If your lawn tractor’s serial number is on the list, or the transmission had been replaced from March 2016 through August 2017, contact your John Deere dealer for more information.

**Remedy:** Consumers should stop using the recalled lawn tractors immediately and contact a John Deere dealer to schedule a free repair. John Deere is contacting all registered owners of the recalled lawn tractors directly.

FOR FURTHER INFORMATION CONTACT Deere & Company at (800) 537-8233 Monday through Friday from 8 a.m. to 6 p.m. and on Saturdays from 9 a.m. to 3 p.m. ET or visit the firm’s Web site at [www.johndeere.com](http://www.johndeere.com).

Post until: **January 20, 2018**

In cooperation with the U.S. Consumer Production Safety Commission and Health Canada