

IMPORTANT SAFETY NOTICE


Emerson Tool Company Announces Voluntary Corrective Action for 6 and 9 Gallon NXT Wet/Dry Vacuums: HD06000 and HD09000

Hazard: The on/off switch can be pulled out in a way that could expose a user to an energized wiring connector, creating a potential shock hazard.

What to do:

Check to see if you have an affected unit and go online at www.emerson.com/en-us/commercial-residential/emerson-tool-company to order a replacement Powerhead Assembly.

Or, contact Emerson Tool Company toll-free at 1-888-847-8718 between 8 a.m. and 5 p.m. CT, Monday through Friday.



CONSIGNE DE SÉCURITÉ IMPORTANTE

Emerson Tool Company annonce une action corrective volontaire pour les aspirateurs de liquides et de poussière NXT de 22,5 litres et 34 litres / 6 et 9 gallons : HD06000 et HD09000

Danger : L'interrupteur marche/arrêt peut être tiré d'une manière qui pourrait exposer un utilisateur à un connecteur de câblage sous tension, créant ainsi un risque potentiel de choc.

Que faire :

Vérifiez si vous avez un appareil affecté et allez en ligne à l'adresse suivante www.emerson.com/en-us/commercial-residential/emerson-tool-company pour commander un ensemble de bloc-moteur de remplacement.

Ou contactez Emerson Tool Company au numéro gratuit 1-888-847-8718 entre 8 h et 17 h, HC, du lundi au vendredi.

